

Structural cracks



Surface cracks



Structural cracks




Surface cracks



Structural & surface cracks



Center anchor & footing to replace at Court# 2





September 17, 2024

Re: Artificial Turf and Tracks with Installation, Related Equipment, Materials and Supplies

To Whom it May Concern:

The AstroTurf response to Sourcewell's Request for Proposal (RFP) 031622 outlines on the contract Questions 26-28 that AstroTurf permits Sport-Tech Acrylics Corp to provide services on behalf of AstroTurf through the contract they hold with Sourcewell. Sport-Tech Acrylics Corp is a distributor for AstroTurf, they are authorized and incorporated into the contract as indicated in the language of the proposal as an authorized distributor.

Contract documentation linked below:

[AstroTurf: Contract 031622-AST | Sourcewell \(sourcewell-mn.gov\)](#)

Sincerely,

**Heidi Murray** | Senior Supplier Development Specialist

Office: 218-895-4119

Website: [sourcewell-mn.gov](https://sourcewell-mn.gov)





410 Route 22, Brewster, NY 10509 - Phone: (914) 232.1640 – Fax (914) 232-1802 - [www.sporttechconstruction.com](http://www.sporttechconstruction.com)

Andrea Russo

Date 11/15/25

Town of Pound Ridge  
179 Westchester Ave.  
Pound Ridge, NY 10576  
Phone# 914 764-3987  
Cell# 914916-0613  
[arusso@townofpoundridge.com](mailto:arusso@townofpoundridge.com)

ID# 116297

We appreciate the opportunity to submit the following proposal for the Installation to TOWN PARK 2 SOUTH TENNIS COURTS  
SOURCEWELL COOPERATIVE CONTRACT # 031622-AST

---

**WE HEREBY SUBMIT SPECIFICATIONS AND ESTIMATES FOR:**

**POWERWASHING OF TWO (2) ALL-WEATHER TENNIS COURTS – Total area comprises approximately (1440) Square Yards.**

1. **PRESSURE WASHING** – Utilizing a walk behind pressure washer, remove all dirt, mildew, and other contaminants for the entire surface area. Thoroughly air blow and clean the entire court surface. (Water to Be Supplied by town at fire hydrant)
2. **LOW SPOT / BIRD BATH REPAIR** – Price DOES NOT INCLUDE PATCHING OF DEPRESSIONS (BIRDBATHS) and other irregularities in the newly installed asphalt receiving surface. This work, should it be necessary, shall constitute an extra charge based on all additional costs including and associated to mobilization(s), labor and materials.
3. **INCLUSION PROVISIONS** – Price does include materials, expenses, prevailing wage labor, freight, taxes, liability insurances and state required worker's compensation.
4. **EXCLUSION PROVISIONS** – Price does not include the cost of bonds, contract specific insurance riders, surveys, in-ground equipment, jobsite security, temporary fencing and permits.
5. Proposal submitted by Michael Edgerton – President, SPORT-TECH ACRYLICS CORP. (CTCB – Certified Tennis Court Builder).

---

**\* NOTE: ALL COLOR WORK AND MATERIALS ARE GUARANTEED FOR ONE YEAR, EXCEPT CRACK REPAIRS IF ARMOR IS NOT USED \***

---

**TOTAL ESTIMATE:**

WE PROPOSE HEREBY TO FURNISH MATERIAL AND LABOR - COMPLETE IN ACCORDANCE WITH ABOVE SPECIFICATIONS FOR THE SUM OF:

**TOTAL –Twenty-Eight Hundred DOLLARS .....\$2,800.00**

Thank you for the opportunity to quote this project for you. We look forward to hearing from you soon. If you have any questions, please do not hesitate to call me at (914) 260-8475.

Sincerely,  
Michael Edgerton, President  
CTCB  
Sport-Tech Acrylics Corp.





P.O. BOX 189 • SOMERS • NY • 10589  
914.248.6825 • Fax 914.248.6824  
Email: [info@ovaltennis.com](mailto:info@ovaltennis.com)

ACRYLIC COLOR SYSTEM – COURTS# 1-2: 120' x 110'

**BASE:**

1. All cuts and cracks greater than 1/4" wide shall be cleaned and filled with acrylic patch mix. **NOTE: Stone dust screenings required to fill wide cracks (and/or significant low areas) prior to patching with acrylic mix.**
2. Brush and scrape up to 200' of structural cracks to remove, as possible, debris and loose material. Fault Line crack repair system intended for long term repairs to asphalt will be installed per manufacturer's instructions. The crack repair systems utilize special fabrics that covers the crack and expands as the cracks widen, especially during the cold winter months. *Crack repair systems prevent immediate return of cracks; however, additional cracks may form and existing cracks may lengthen. Crack repair systems will not permanently bridge cracks resulting from sub-surface movement. See: <http://ovaltennis.com/crack-repair/>*
3. Birdbaths shall be marked by flooding court, and then filled with trowel patch in 1/4" lifts. Most depressions will be reduced but some may remain due to overall slope irregularities. **Note: Up to two (2) days included in contract cost for leveling depressions. Depressions will be minimized; however, some depressions and birdbaths holding water after rain will remain.**
4. All works to be performed on the inside of court fence line. Any additional works outside of fence line is considered extraneous and at an extra cost when requested by court owner, unless otherwise noted.
5. **OPTIONAL: FIBERGLASS FABRIC (120' X 110'):** Tented "craze" cracks to be stoned down by hand and/or stoning machine to reduce lumps and uneven areas. Plexibond Coating shall be diluted with water and applied to court utilizing a "wet on wet" method ("direct painting"). The fiberglass membrane shall be rolled out into the Plexibond and stretched tightly over surface. Any adjacent panels shall be overlapped a minimum of 3". Wrinkles in the membrane shall be corrected, as feasible, by pulling and rolling. Membrane and Plexibond will need to cure prior to application of resurfacer coats. Fabric will be applied to entire surface. *Crack repair systems can help to prevent immediate return of cracks; however, additional cracks may form and existing cracks may lengthen. Fiber may lift and/or tear if court is experiencing significant subbase movement.* **TWO** coats of **FLEXIBLE** acrylic resurfacer will be applied to correct minor surface irregularities and to seal existing surface (in place of one coat, standard AR).

**ACRYLIC COLOR FINISH: NOVACRYLIC COMBINATION SURFACE–**

1. Entire surface shall be pressure washed to remove as much loose paint, dirt and deteriorated asphalt as possible. Any small areas of peeled, chipped or bubbled paint will be hand scraped and tacked with *Nova Bond* acrylic (*if there is an excess of peeling or loose paint, there will be an additional charge for labor and disposal*). **Note: Site owner must supply water source adjacent to courts for pressure washing and tool maintenance. If insufficient water pressure is found to delay court cleaning, an additional cost may apply.**
2. **One** coat of acrylic resurfacer will be applied to correct minor surface irregularities and to seal existing surface. **Note: Recently the incidence of aggregate utilized to manufacturer asphalt containing trace amounts of iron (pyrite) has increased. Neither the asphalt plants nor Oval Tennis has control of iron in the asphalt mix. If the asphalt does contain iron, small rust spots may appear in the acrylic color. These do not affect play, but appear as surface stains.**

4. *Multiple applications of acrylic increase possibility of acrylic bubbling, especially in presence of significant ground water. This occurs when subsurface moisture is vaporized by solar heat and cannot escape rapidly enough thru the acrylic coating.*
5. Oval cannot be responsible for bubbling and moisture permeating surface of court after new acrylic system is applied. There are a multitude of variables constantly changing and evolving in the life span of a court and the movement of subsurface water. Proper drainage is required to remove subsurface water from settling under the courts; drainage at courts is unknown at this time. Oval Tennis cannot be responsible for subsurface water which may freeze and cause cracking in asphalt surface. **Oval is not responsible for any future wrinkling, raised or bubbling crack repair fabric due to trapped moisture or water under existing court.** *Oval Tennis cannot be responsible for future conditions at asphalt after paint layers are applied.*

**CONDITIONS:**

1. **Bear in mind that Oval Tennis, Inc. is an open shop and our employees are non-union. NYS prevailing wages rates for Operating Engineer, Teamsters, General Laborer, and Painters are included in the estimated cost. Any additional costs related to local union trade requirements or on site will be an additional charge to site owner.**
2. **Property owner must ensure that landscape sprinklers do not reach court during scheduled repairs.** Repair of damage caused by sprinkler system operation will advance completion date and be an additional charge based on time and material.
3. Court color(s) must be indicated on signed contract. Any changes to final color will be invoiced at \$2,200. per additional surfacing layer per court for restocking and redelivery of new paint. Chips on color chart are actual samples of paint provided by Nova Sports USA, however, disparity between chip size and court size as well as ambient light conditions will affect color perception. Should colors be altered after court is completed, cost will be determined by several variables (i.e., how many layers are required for adequate coverage, in or out of bounds alteration, if lines are reapplied, etc.).
4. Court owner should not use shovels or snow blowers on court to remove snow; landscaper equipment with tires should not be used on court. Tennis shoes only should be used on court. Any other shoe or equipment is not recommended unless proper protection has been applied or special coating with additional acrylic has been applied. Heavy items left on court can leave marks and depressions. Paint is delicate and can be scraped off of asphalt without proper caution and care.
5. **Court owner is responsible for informing landscapers to stay off tennis court during works. Any grass cutting or blowing of leaves should be aimed away from court. Any debris (grass and/or leaves) that are blown onto the court during installation of paint layers will result in additional works and costs to court owner for any extra coats of paint and for labor required to repair.**
6. An additional administration fee of \$1,250 will apply to AIA Form billing requirements. If retention is not paid in a timely manner as per contract, an additional charge of \$950 will also be applied.

Sport Court Resurfacing LLC  
Austin Gardella  
23 Arrow Head Dr, Stamford CT 06903  
GardellaAustin@gmail.com

August 27, 2025

Attn: Town of Pound Ridge Recreation

RE: The four tennis courts in the rear of the Pound Ridge town park are playable and safe. The asphalt of the court is in stable condition with only 100 feet of cracking on the front two courts. There is also multiple surface pitting and small cracks on the first two courts that can be addressed with resurfacing. The rear two courts are in great shape, but moss and mold have ruined the painted surface near the backboard. The Courts are surrounded by trees so moss and mold are a recurring issue. Excess powerwashing of courts over the years has made the top coating very thin and resurfacing is necessary to extend the life of the asphalt courts.

**Sport Court Resurfacing Proposes to Resurface the 4 courts at Pound Ridge Town Park with the following specifications:**

**Front two courts:**

- Powerwash cracks and molded areas
- Machine sand entire surface with 18 grit sand paper
- Patch all cracks with acrylic patch binder mix, machine sand patches
- Use riteway crack system over all patches. Apply two coats of resurfacer over all patches.
- Two coats of Black resurfacer over entire surface
- Two coats of an acrylic coating over entire surface, two colors will be used for playing area and outside area of the court.
- Stripe courts for Tennis

**Rear two courts:**

- Powerwash molded areas
- Machine sand entire surface with 18 grit sand paper
- Two coats of green tinted resurfacer over the back section of the court



# SALES QUOTE

Sales Quote Number: S-QUO2994  
 Sales Quote Date: 9/4/2025

*Commercial Aquatic Systems & Supplies*

## Sell

To: Pound Ridge, Town of  
 179 Westchester Ave.  
 Pound Ridge, NY 10576  
 USA

## Ship

To: Pound Ridge, Town of  
 Andrea Russo  
 179 Westchester Ave.  
 Pound Ridge, NY 10576  
 USA

FOB:  
 Terms Net 30

Customer ID C00541  
 SalesPerson Phil Mylod

Item No.	Description	Unit	Quantity	Unit Price	Total Price
20-000	Misc. Filtration Systems/Parts	Each	34	669.375	22,758.75
	Mermade DE filter part. 38x48CBOCOMP. Included in each part is a filter grid, cover and gaskets.				
20-000	Misc. Filtration Systems/Parts	Each	68	37.625	2,558.50
	Mermade clamps for DE filter grids.				
HANDLING	Handling		1	7.95	7.95
SHIPPING	Shipping		1	1,000.00	1,000.00
	Estimated shipping of complete grids and clamps.				
INSTALLATION	Installation	Each	40	145.00	5,800.00
	Estimated removal of old grids and installation of new grids/parts is (2) days. Plan on (2) men, (10) hour days. (40) hours total is the estimation. Installation may take less time if no problems arise or more time if unforeseen issues arise. Time starts when crew leaves North Haven, CT main office and ends when crew returns to North Haven, CT office.				

<b>Subtotal:</b>	<b>32,125.20</b>
Invoice Discount:	0.00
Total Sales Tax:	0.00
<b>Total:</b>	<b>32,125.20</b>

Remit To Address:  
 Streamline Aquatics  
 PO Box 130  
 Northford, CT 06472

All past due invoices will carry a sevice charge of 1.5% per month (18%) per annum.

Phone #	Fax #	Web Site
(860) 430-1255	(860) 430-1251	www.streamlineaquatics.com

Strongman Pool Services

44 Ridgecrest Rd  
Putman Valley, NY 10537  
(914) 275-2291  
strongmanservices@yahoo.com  
strongmanservices.com

QUOTE

Quote Number  
# 624

Quote Total  
\$50,895.00

Bill To:  
Town of Pound Ridge  
179 Westchester Ave  
pound Ridge, NY 10576

Quote Date  
August 26, 2025  
Expiration Date  
November 30, 2025

LOCATION: 179 Westchester Ave, pound Ridge

Item	Description	Qty	Rate	Amount
Filter Repair	Removal & replacement of all 50 D.E filters grids for both pools. This cost includes all materials complete grid assembly (internal grid, jacket, gaskets & clamps)	1	49,000...	49,000...
Flang Repair	Resealing of two mechanical flange connections that are failing please see photos includes new, gaskets and stain steel bolts, and washers. This price is based on all filter grids being replaced.	1	1,895.00	1,895.00

Subtotal\$50,895.00

Tax\$0.00

Quote Total\$50,895.00

Strongman Pool Services

strongmanservices@yahoo.com

Name & Signature

Date





# SALES QUOTE

Sales Quote Number: S-QUO3029  
Sales Quote Date: 9/18/2025

*Commercial Aquatic Systems & Supplies*

## Sell

To: Pound Ridge, Town of  
179 Westchester Ave.  
Pound Ridge, NY 10576  
USA

## Ship

To: Pound Ridge, Town of  
Andrea Russo  
179 Westchester Ave.  
Pound Ridge, NY 10576  
USA

FOB:  
Terms Net 30

Customer ID C00541  
SalesPerson Phil Mylod


Item No.	Description	Unit	Quantity	Unit Price	Total Price
20-000	Misc. Filtration Systems/Parts	Each	2	47,555.10	95,110.20
	Stark SS Series Top-Conx / End Manway Filter System 40 SF Total Area, Manual Single-Knob Backwash (CM200): Incl (2) SS72 Horz Filter, 42" Dia X 20 SF, 100-PSI Rating, Clear Viewport Manways, Diaphragm Valve Piping Kit (preglued manifolds) w/ 6" Inf/Eff & Waste Flgs, (2) 6" Clear Backwash Valves, (1) 6" Priority Valve, Sight Glass/Spool, and Inf/Eff Gages, 6" Flow Sensor w/Mounting Saddle and Temperature Sensor				
20-300	Para-Pump Booster Pump System, PBS01	Each	2	1,784.70	3,569.40
INSTALLATION	Installation	Each	1	57,500.00	57,500.00
	Estimated installation costs. Rig in new filters (On site as we arrive). Pipe new filters and install new valves. Supply and install filter media. Start up filter systems and review proper operation with owner. Streamline Aquatics not responsible for permit plans or approvals. Any electrical work to be completed by owner.				
HANDLING	Handling		1	7.95	7.95
SHIPPING	Shipping		1		
	Shipping costs to be determined at time of shipping.				

<b>Subtotal:</b>	<b>156,187.55</b>
Invoice Discount:	0.00
Total Sales Tax:	0.00
<b>Total:</b>	<b>156,187.55</b>

Remit To Address:  
Streamline Aquatics  
PO Box 130  
Northford, CT 06472

All past due invoices will carry a service charge of 1.5% per month (18%) per annum.

Phone #	Fax #	Web Site
(860) 430-1255	(860) 430-1251	www.streamlineaquatics.com



74 HICKORY LANE, BETHLEHEM, CONNECTICUT 06751 • (860) 274-7903 • FAX: (860) 274-7902  
HIC #567297 • PLM. #280149  
WWW.DRAKELEYPOOLS.COM

## POOL FILTRATION RENOVATION

Town of Pound Ridge  
179 Westchester Avenue | Pound Ridge, NY  
Attn: Andrea Russo

### SCOPE OF WORK

#### POOL FILTRATION RENOVATION:

- Remove piping interior of both VAC DE filter tanks for competition and recreation pools. Assist Parks and Rec in cleaning out tanks and removing debris.
- Remove both pool vac DE pumps, keep backwash pumping station. Supply and return hydraulic loops to remain with valving.
- Core drill existing tanks for new suction and pressure outlets.
- Install Schedule 80 new tank fittings including antivortex prevention, link seal and diverter/displacement piping from the ASR double channel perimeter gutters.
- Apply to the tank interiors a new white sealant after the installation of the cementitious filling of the cored areas.
- Deliver (2) high-pressure, stainless-steel filter tanks for both pools (crane costs of hoisting for one day included). Install on new filter area outside of the filter building.
- Furnish and install 2 new high-rate variable speed filter pumps with strainers and new valving inside mechanical room.
- Run new return discharge piping from new filter pumps to new filter area and reconnect to existing effluent side piping in pipe chase.
- Provide (2) variable speed electrical controllers for both new filter pumps to monitor and control energy consumption (to be wired by Town electrician).
- Connect both new systems to newly aligned surge tanks and existing effluent side piping.
- Run new backwash piping into existing setting tank and connect new suction from tank to existing backwash piping pump. Discharge stand piping to remain.
- Paint and label piping according to County protocol. All piping to be Schedule 80, 8" with tees and bypass 8" valving.
- Flow to be designed for a 360-minute, 6-hour turnover and comply with County regulations.
- Existing sanitation, flow meters, chemical controllers to remain.
- After pools are cleaned and filled in the Spring by Town, start up new systems and instruct.

**Cost: \$272,500.00**

#### NOTES:

1. All costs are estimated on a portal-to-portal basis. Any additional work not mentioned above will be invoiced on a time and material basis, including travel time. Our crew rates are billed at \$225.00 per hour per crew.
2. This is a special request design/build proposal. This scope of work is not for redistribution or bidding and is proprietary in nature.



C/O MRC  
PO Box 106  
Spring Lake, NJ 07762  
Ph: 732-458-1111  
Em: MRC@GAMETIME.COM  
Web: www.mrcrec.com

09/05/2025  
Quote #  
118996-01-01

## NY Pound Ridge Town Park Swings

Pound Ridge Town of  
Attn: Andrea Russo  
179 Westchester Avenue  
Pound Ridge, NY 10576  
United States  
Phone: 914-764-3987  
arusso@townofpoundridge.com

Ship to Zip 10576

Quantity	Part #	Description	Unit Price	Amount
1	RDU	GameTime - TOW BAY PRIMETIME SWING FRAME WITH (4) BELT SEATS- FRAME COLOR _____ (1) 5320 -- 8' ADA Primetime Swing Frame (1) 5321 -- 8' ADA Primetime Swing Add-A-Bay (4) 5287 -- Belt Seat for 8' Toprail	\$5,232.00	\$5,232.00
1	INSTALL	GameTime - BY A CERTIFIED INSTALLER- INCLUDES • Offloading upon delivery • Installation of Swings • Removal and disposal of packaging materials	\$5,000.00	\$5,000.00
			<b>Sub Total</b>	\$10,232.00
			<b>Material Surcharge</b>	\$177.89
			<b>Freight</b>	\$1,499.13
			<b>Total</b>	\$11,909.02

### Comments

SITE WORK AND SAFETY SURFACING ARE NOT INCLUDED IN THIS PROPOSAL

TAX EXEMPTION CERTIFICATE IS NEEDED WHEN ORDERING OR TAXES MAY BE APPLIED

MS/hd





## Sales Proposal

Town of Pound Ridge  
Town House  
Andrea Russo  
179 Westchester Ave.  
Pound Ridge, NY 10576

Quote No. SP157752-1  
Customer No. 49688  
Document Date 09/17/2025  
Expiration Date 11/16/2025

Sales Representative Danicka Russo  
Email DanRus@Kompan.com  
Phone No. 914-714-8396 / 800-426-9788

Project Name US339039 Town Park New Swing Area

No.	Description	Qty Unit	Unit Price	Discount %	Net Price
<b>Omnia Partners Contract #2017001135</b>					
<u>KSW924-CUSTOM</u>	CUSTOM - Swing Frame, 4 Seat, 8 ft H In-ground 90cm 20405782	1 Pieces	6,810.00	10.00	6,129.00
					
INSTALL SPECIAL	Installation of KOMPAN Equipment Prevailing wage	1 Pieces	7,980.00	5.00	7,581.00
US-EXCAVATION	Excavation of area up to 1175SF up to 12"	1,175 Sq. Feet	8.50	5.00	9,488.12
US-TFG-CUSTOM	Engineered Wood Fiber (EWf)/ FF up to 14" compacted to 12" + Filter Fabric	1,175 Pieces	1.55	10.00	1,639.12
					
US-TFG-FREIGHT	Freight for EWf Surfacing	1 Pieces	560.00		560.00
INSTALL SPECIAL	Installation of EWf/FF At Prevailing Wage	59 Pieces	38.00	5.00	2,129.90
INSTALL SPECIAL	Wood Timbers 6x6 + Installation	140 Pieces	56.00	5.00	7,448.00
US-DEMO	Dumpster Fee + Removal of Spoils	2 Pieces	2,500.00	5.00	4,750.00
FREIGHT	Freight	1 Pieces	1,362.00		1,362.00

Description	Qty	Retail Price	Discount	Net Price
No. of Products	1			
Subtotal - Products		6,810.00	681.00	6,129.00
Subtotal - Sitework		14,987.50	749.38	14,238.12
Subtotal - Surfacing		2,381.25	182.13	2,199.12
Subtotal - Installation		18,062.00	903.10	17,158.90
Subtotal - Freight		1,362.00		1,362.00
<b>Total USD</b>				<b>41,087.14</b>

**Payment Terms** 50% Prepayment , 50% Net 30 days

KOMPAN, INC. | 605 W Howard Lane Ste 101 | Austin, TX 78753 | USA | Phone No. 1-800-426-9788  
E-Mail Contact@KOMPAN.com | www.KOMPAN.us

SWIFT Code NDEAUS3N (Nordea Bank, NY | Bank Account No. USD 718 155 3001 | Routing No. 026010786)



**SITE SPECIALISTS**  
NEW YORK

265 Post Avenue, Westbury, NY 11590  
516-338-1630 (office) 516-338-1631 (Fax)

**landscape  
structures™**

ALL PURCHASE ORDERS, CONTRACTS,  
AND CHECKS TO BE MADE OUT TO:  
LANDSCAPE STRUCTURES, INC.  
601 7TH STREET SOUTH  
DELANO, MN 55328 U.S.A.  
763-972-3891 800-328-0035  
Fax: 763-972-3185

## PROPOSAL

1/9/2023

PO #

CONTACT: Andrea Russo  
PHONE: 914 764-3987  
FAX: \_\_\_\_\_  
email: Doolberg@townofpoundridge.com

Destination: PoundRidge, NY

FREIGHT ☒ Prepaid ☐ Collect

SHIP TO: TBD

TBD  
TERMS (Subject To Credit Approval By LSI)  
6+ Weeks  
SHIPPING TIME  
Equipment Pricing Good for 60 Days from Date of Proposal  
All Other Pricing Good for 60 Days from Date of Proposal

BILL TO: TBD

We are pleased to submit this proposal to supply the following items:

QTY	ITEM NO.	DESCRIPTION	UNIT PRICE	EXTENDED AMT
<b>Project: PoundRidge Park</b>				
1	6590	Single Post Arch Frame (2) swing bays (4) belt seats proguard chains	3,760.00	\$ 3,760.00
1	install	Site work, installation and surfacing performed by Landscape Structures Certified Installer	32,704.96	\$ 32,704.96
1	Removal	Discard of excavated spoils	6,126.12	\$ 6,126.12
1	Discount	Discount as per SourceWell Purchasing Contract	(225.60)	\$ (225.60)
			-	-

SIGNATURE BELOW ACCEPTING THIS PROPOSAL WILL CONSTITUTE A PURCHASE  
ORDER ONLY UPON APPROVAL BY LANDSCAPE STRUCTURES, INC. CUSTOMER  
RECEIPT OF AN ORDER ACKNOWLEDGEMENT CONSTITUTES SUCH APPROVAL

Shipping packages are usually heavy and awkward and require mechanical handling to accomplish truck  
unloading at destination. Truck unloading and job site work are extra and not included.

ACCEPTED BY CUSTOMER \_\_\_\_\_ DATE \_\_\_\_\_

INSTALLATION See Above

PRINT NAME \_\_\_\_\_

FREIGHT \$1,012.85

PROPOSED BY LSI REPRESENTATIVE \_\_\_\_\_ DATE \_\_\_\_\_

SALES TAX N/A

PRINT NAME \_\_\_\_\_

TOTAL \$ 43,306.74

Issue PO, deposit and all documentation to:

Landscape Structures, Inc.  
601 - 7th Street South  
Delano, MN 55328-0198  
763.972.3391

Send Order (for processing) to:

Site Specialists, Ltd.  
265 Post Avenue, Suite #365  
Westbury, NY 11590  
516-338-1630 Fax 516-338-1631  
Package to include signed PO, Deposit, Tax Exempt,  
and approved shop drawings.

Pound Ridge Park  
Pond Ridge NY

### Scope of Work

Excavate and grade approx. 1,152 SF area. Excavated spoils to be stockpiled onsite.  
Unload delivery of swings and dispose of packing material.  
Furnish and install 136 LF of wood timber border. Height to be 2-3 courses as needed. Install  
only: two-bay single post swing with belt seats.  
Furnish and install 1,152 SF of 12" depth wood fiber surface with one layer of geotextile  
Fabric.  
Seed and restore lawn areas disturbed by construction.

Dispose of excavated spoils.